Masango, Vusi

From: Hinsch, Manda

Sent: 19 June 2014 03:10 PM

To: PBulterman@Barloworld-equipment.com

Cc: du Toit, Donne

Subject: 465044 ESKOM Cashan Substation and Powerline

Attachments: 465044_2014_05_26_Amended_data_Affected_Adjacent.pdf

Dear Peter

Following our telephonic conversation herewith a brief summary of the project and attached map.

Eskom is currently trying to decrease the pressure exerted on other power stations by supplying additional substations to areas in need and supplying electricity to areas with increasing electricity demand in the North West and Gauteng Province.

The proposed project includes the construction of a substation in Cashan and a powerline to the existing Hekpoort substation. The proposed Cashan substation falls within the Gauteng province, North West of Krugersdorp and is intended to alleviate the pressure exerted on Eskom in the area for increased power supply and to attempt to ease pressure this increased power supply is exerting on other power stations.

The proposed Cashan substation will be connected to the existing Hekpoort substation via a 132KVA powerline which runs approximately 9 km in a North Easterly direction from Cashan into the North West Province. Figure 1 shows the location of the substation and powerline. Please see map

Please contact me should you require further info, please contact me

Manda Hinsch BSc. Hons, Pr. Sci Nat, FWISA Associate Partner/Principal Scientist



SRK Consulting (South Africa) (Pty) Ltd.

Menlyn Woods Office Park , Block A , 291 Sprite Ave , Faerie Glen P O Box 35290, Menlo Park, 0102

Tel: +27 12 361 9821; Fax: +27 86 5709573

Mobile:+ 27 82 808 9938 Direct:

Email: hinm@srk.co.za

www.srk.co.za

This transmission is intended for the sole use of the addressee, and may contain information that by its privileged and confidential nature is exempt from disclosure under applicable law. You are hereby notified that any dissemination, distribution or duplication of this transmission by someone other than the intended recipient or its designated agent is strictly prohibited. If you have received this transmission in error, please notify the sender immediately by replying to this transmission, or by collect call to the above phone number.

Please consider the environment before printing this e-mail